(10/25/2010) Paul Baker - Fwd: quarry clean up

M/039/0013
Page 1

From:

John Blake Paul Baker

To: Date:

10/25/2010 11:24 AM Fwd: quarry clean up

Subject: Attachments:

FAYETTEOCT1810 (45).jpg; FAYETTEOCT1810 (40).jpg; FAYETTEOCT1810 (17).jpg;

FAYETTE0CT1810 (3).jpg; FAYETTE0CT1810 (19).jpg; Sonia Wallace.vcf

FYI

>>> Sonja Wallace 10/20/2010 4:20 PM >>>

Ron, tom and I were out at the Fayette Quarry this past mon and tues doing clean up work. It appears that there is more infrastructure and garbage that initially thought.

We took 2 large loads of trash to the landfill and a full load to the metal recyclers in town. We also removed all of the used oil and dropped off to a recycler in SLC. We removed as much garbage as we could pull out. By pull out, I mean, that it appears that the Lessee decided that it would be easier to bury the contents of the previous building than remove it. Much has been covered over with quarry rock using a back hoe or another type of large equipment. I have several bills with his name or company on that were buried.

As far as remaining infrastructure, there is a large underground storage tank, (approx. 30,000 gallon) and piping on top of a hill just west of where the building was located that will need to be removed. The tank was empty but smelled of hydrocarbons. There was an above ground tank (approx 10,000 gallons) on the site next to a water spigot that appeared to be used for water storage. I took several GPS points of objects at the site and will send to you when I get if from Kate. I GPS'd the building corners to give an idea of how much concrete is there. There is a great deal of wiring (buried) still in place around the concrete pad that will need to be removed. Isn't there a water well at the site? Do you know where this is located? Can you send the info on this, as this will need to be properly closed. These are all things (including removal of remaining garbage) that the bond is going to need to rectify.

Do you have an operations plan? If you could get that to me, that may also identify other aspects of his operations that we are not aware of.

Any updated info on the bond? Do you want me to work with DOGM on the clean up or will you do this? If you choose to oversee work, I want to be at the site during the remedial work to inventory what else is found and ensure work is done properly. There are a few areas of stained soil that will need to be removed and we may find more as the rubble is removed from the trash. there is some evidence (misc. parts) that a semi may be buried there.


If you want to meet and discuss next steps, perhaps Monday with Tom and Ron and I? Please let me know.


I have attached some photos.

Thanks for your help.

Sonja F. Wallace **Environmental Compliance Manager** Utah School and Institutional Trust Lands Administration (SITLA) 675 East 500 South

Salt Lake City, Utah 84102 801-538-5108/801-707-6185 (c) swallace@utah.gov





S2SW4 (Within), Section 32, Township 19 South, Range 1 East, SLB&M, Oct. 21, 2010 SITLA

Lot 4 (Within), Section 5 Collected Data





Land Ow nership and Administration

Bureau of Land Management

Bureau of Reclamation

Bankhead Jones Land Use Lands

National Recreation Area

National Parks, Monuments & Historic Sites

National Forest

National Widelenses Area

National Widelenses Area

National Widelenses Area

Other Ereich Refuge

Other Ereich Refuge

Other Federal
Military Reservations and Corps of Engineers
Private

Frivate
Sate Trust Lands
Sate Sovereign Land
Sate Parks and Recrosion
Sate Wildlife Reserve/Management Area
Other Sate
Tribal Lands



Data represented on this map is for REFERENCE USE ONLY and is NOT to be used in place of a legal land survey! The Utah school and Institutional Trust Lands Administration SHTA.) IT/GIS Department assumes no responsibility for errors or omissions in these materials. Land purcels, leave boundaries and associated SHTA. A data layers may have been adjusted to slight with other ligital features (i.e. PLSS lines, digital imagery, roads) or other ise points in order to allow for visual "best fir! While SHTA seeks to energy data for accuracy and content, discrepancies may exist within the data SHTA hereby disclaims any and all liability due to the sace or misuse of this map and the data represented on this map. The user assumes total responsibility for verification and use.

Lakes, rivers, streams, highways, roads, county and state-bound aries were USGS D.I.G. 1:100,000 source files, and contour lines (if person) were generated from USGS DBM. 3-arc-second files, collected and distributed by the Usih Automated Geographic Reference Context. The ownership information was originally digitated by Usih State University from BLM 1:10:000 source mays and has been edited by Usih Trust Lands Administration (T.I.A) to reflect current state ownership. T.I. A surface and mineral ownership is frequently being updated and verified by T.I.A. Official and detailed information is available from the responsible agencies. Color Aerial Photo (National Agricultural Imagery Program, NAIP 2009).